



# Peru CSO Overflow Inspection

Date Bypassed: 3/20/2017

	Rainfall Amount	CSO Discharged	Condition of Receiving Stream	Sewer related debris present	Remarks
	0.80				
<b>West Reveene CSO's</b>					
WR-1					
WR-3					
WR-4					
WR-4A					
WR-6					
<b>East Reveene CSO's</b>					
ER-1A		Yes			
ER-1B		Yes			
ER-2		Yes	Clear	No	
C-5					
ER-2A					
ER-4					
<b>IMC-1</b>		Yes			
<b>Illinois River CSO's</b>					
IR-1					
IR-2					
IR-3					
IR-4					
IR-5		Yes	Clear	No	
IR-6A					
IR-7					
IR-8					
IR-9		Yes	Clear	No	
IR-9A		Yes	Clear	No	
IR-10		Yes	Clear	No	