



Peru CSO Overflow Inspection

Date Bypassed: 3/27/2017

	Rainfall Amount	CSO Discharged	Condition of Receiving Stream	Sewer related debris present	Remarks
	1.00				
West Reveene CSO's					
WR-1					
WR-3					
WR-4					
WR-4A					
WR-6					
East Reveene CSO's					
ER-1A					
ER-1B					
ER-2					
C-5					
ER-2A					
ER-4					
IMC-1		Yes			
Illinois River CSO's					
IR-1					
IR-2					
IR-3					
IR-4					
IR-5					
IR-6A					
IR-7					
IR-8					
IR-9		River Backed Up Against Gate			
IR-9A		Yes	Clear	No	
IR-10		Yes	Clear	No	